MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIAL

DATE OF PREP 10 - 81 (Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA

Section I

BOSTIK WEST, DIV. OF USM CORPORATION, AN EMHARY U MANUFACTURER'S NAME

STREET ADDRESS 20846 So. Normandie Ave. CITY, STATE, AND ZIPCODE TOTTANCE, Ca.

Catalyst for all DPM 110 Semi-gloss Colors

320-6800 EMERGENCY TELEPHONE NO. (213)

PRODUCT CLASS

AMINE ABDUCT.

BOSTIK TRADE NAME

MANUFACTURERS CODE IDENTIFICATION Catalyst for: 453-3-Series, 463-3-Series 463-3-8, 454-3-Series. Mix Ratio: '3 parts

Base to 1 part CA-118 by volume.

Section II — HAZARDOUS INGREDIENTS

INGREDIENT CA-118 Epoxy Catalyst	CAS No.	PERCENT	T PPM	mg/M³	LEL	VAPOR PRESSURE IIIII Hg.
Methyl ethyl ketone	78-93-3	25-30	200		1.8	70.0
Butyl alcohol	71-36-3	20-25	100		1.7	4.0
Butyl acetate	123-86-4	20-25	150		1.7	8.0
B u t yl cellosolve	111-76-2	10–15	50		1.1	1.0
Toluene	108-88-3	< 5.0	200		1.2	22.0
Diethylenetriamine(DETA)	111-40-0	Trace	1.0		1.4	<1.0
						÷

Section III — PHYSICAL DATA

BOIL	ING	RANGE	

176-340° F.

VAPOR DENSITY

HEAVIER

LIGHTER, THAN AIR

EVAPORATION RATE

FASTER

X SLOWER THAN ETHER

PERCENT VOLATILE BY VOLUME

87%

WEIGHT PER GALLON 7.0 lbs.

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

Red Label, Flammable

(Min) FLASH POINT

23° F. Tag Closed Cup

LEL 1.1

EXTINGUISHING MEDIA

Exclude air - Use foam, CO₂, steam, water fog,

dry chemicals. Do not use water.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Vapor forms explosive mixture with air between

upper and lower explosion limits.

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water, exclude air, use water spray to cool fire exposed surfaces and to protect personnel.

Section V — HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE: See Section II EFFECTS OF OVEREXPOSURE: Headache, nausea, dizziness. Breathing vapor will be irritating to nose, throat, and eyes.
Emergency and first aid procedures: Skin Exposure: Wash affected area with soap and water.
Eye Exposure: Flush with water for at least 15 minutes, consult physician. Ingestion: Consult physician immediately. Inhalation: Remove victim to fresh air., consult physician.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE XXX STABLE CONDITIONS TO AVOID: Storage at high temperatures. Incompatability(Materials to avoid): Strong oxidizing agents. Sparks & open flame
Hazardous Decomposition Products: On combustion CO, CO ₂ , Aldehydes and other organics, oxides of nitrogen. HAZARDOUS POLYMERIZATION MAY OCCUR XXX WILL NOT OCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
Prevent liquid from entering sewers, water sources, or low areas. Keep unnecessary personnel away but off source, if possible to do so without hazard. Contain spilled liquid with sawdust, sand of waste bisposal methods. Wash area with detergent & water.
Consult disposal expert and ensure conformity with local regulations.
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mask if used in non-ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
VENTILATION : Face velocity $>$ 60 fpm in confined area

Protective Gloves: Chemically resistant gloves.

EYE PROTECTION: Chemical splash goggles or face shield.

OTHER PROTECTIVE EQUIPMENT: Eye bath & Safety Shower.

Section IX — SPECIAL PRECAUTIONS

PR#CAUTIONSTO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use. Do No handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied - these containers retain product residues (vapor, liquid, etc.)

'All handling equipment should be electrically grounded. Treat as a very flammable liquid.

Lee A. Dickinson

Technical Service Manager